# 1040 CANE RUN ROAD

## 44 +/- Acres


### Georgetown, Scott County, Kentucky



Offered Exclusively By



www.kyhorsefarms.com 518 East Main Street • Lexington, Kentucky 40508 • (859) 255-3657



Justice Real Estate is honored to offer this spectacular and unique property for your new Kentucky home and horse farm. Idyllically located just off Iron Works Pike and less than 7.5 miles from the Kentucky Horse Park, this 4,300 square foot custom-built home sits on some of the best land in Kentucky. This wonderful home, constructed by highly respected builder Gene Coppinger, was professionally designed by well-known architects Clyde Carpenter and Scott Guyon.

Featuring oak flooring on both levels, vaulted ceilings, and a great floor plan, this magnificent three-bedroom, three-and-a-half bath home has been meticulously maintained and loved by its only owner.

A gated stone entrance via a mature tree-lined drive leads you to this special home and a David Rice-built 6 stall barn.

#### <u>First Floor</u>

**Entrance Hall:** 12.75' x 18'. Centered by its see-through wood-burning fireplace and featuring oak floors. It also features two closets, entry door with side panels and transom.





**Living Room:** 14.75' x 24'. Open to dining room, sitting room, and entrance hall. 26' twostory ceiling, oak floor, and floorto-ceiling Peachtree windows. (In fact, all windows and doors are Peachtree.)





**Sitting Room:** 13' x 17' with oak floor and built-in cherry cabinet entertainment center. Recessed lighting and 10.25' ceiling.

**Dining Room:** 13.5' x 15' with oak floor and open to living room and adjacent to the kitchen, recessed lighting and 10.25' ceiling. Fabulous views!





**Kitchen:** 16.5' x 20.5' with breakfast nook and oak floor, Bosch dishwasher, Sub-Zero refrigerator/freezer, range, and microwave. Built-ins and loads of countertop space.

Adjacent 5.25' x 10' pantry with oak floor. Back hall leads to a 7.67' x 9' laundry with sink and tile floor, a full bath, and oversized 2-car garage.

Rear hallway contains a powder room with marble floor and large storage closet and leads to the cozy 12.75' x 20.75' **family room** with oak floor.



The family room offer fabulous views with French doors that lead to a patio with Italian pavers and contains an Irish "Waterford" wood-burning stove.





#### Second Floor







**Library:** 14' x 17.5', overlooks the living room, vaulted ceiling. Bookcases will remain. Open to hallway with two closets and French door to the front balcony.

#### **Master Suite:**


**Bedroom:** 12.75' x 20.75', oak floor, vaulted ceiling, French door to balcony overlooking the rear of the farm.



 $11.75^{\prime}\,\mathrm{x}$  12.75 walk-in closet with oak floor.

**Master Bath:** 12.75' x 12.75' with marble floor and vanity, whirlpool tub with marble surround and separate shower. Vaulted 14.5' ceiling.

R R R



**Shaker Bedroom:** 12.75' x 20.75' with oak floor, vaulted ceiling, double closets, and balcony.









**Amish Bedroom:** 12.75' x 15.75' with oak floor and vaulted ceiling.



**Lower Level** contains a 385 square foot exercise room (not included in the home's square footage) with concrete block walls and painted floor.

There are also three crawl spaces.





13.3' x 20' **rear patio** access via the kitchen and garage. This lovely patio is constructed with Italian pavers.



• 38' x 56' David Rice-built frame horse barn with 6 stalls measuring 11' x 13.5'; a wash stall; 13' aisle; and feed/tack room.





- Jack Hart-built frame run-in shed
- 4 paddocks
- 2 Nelson waterers
- City water
- Excellent soils with 50% Maury Silt Loan and 2 to 6% slopes—wonderful!




Offered Exclusively By


PRICE: \$1,295,000.



Bill Justice, Agent 859-255-3657

www.kyhorsefarms.com 518 East Main Street • Lexington, Kentucky 40508 • (859) 255-3657









Map unit symbol	Map unit name	Rating	Acres in AOI	Percent of AOI
Hu	Huntington silt loam, 0 to 4 percent slopes, occasionally flooded	All areas are prime farmland	7.0	16.2%
McC	McAfee silt loam, 6 to 12 percent slopes	Farmland of statewide importance	14.6	33.9%
uBImB	Bluegrass-Maury silt loams, 2 to 6 percent slopes	All areas are prime farmland	21.5	49.9%
Totals for Area of Interest			43.1	100.0%



#### SELLER'S DISCLOSURE OF PROPERTY CONDITION

This form applies to residential real estate sales and purchases. This form is not required for:

1.	Residential	purchases of new construction	homes if a written	warranty is provided;
----	-------------	-------------------------------	--------------------	-----------------------

2. Sales of real estate at auction; or

3. A court supervised foreclosure.

The information in this form	is based upon the undersigned's ob	oservation and knowledge	about the property	during the period	
	or her purchase of the property on	1989		01/13/2020	
		(Date of purchase)		(Date of this form)	
PROPERTY ADDRESS:	1040 Cane Run Rd. Geo	rgetown, KY 40324		*	

PURPOSE OF DISCLOSURE FORM: Completion of this form shall satisfy the requirements of KRS 324.360 that mandates the seller's disclosure of information about the property he or she is about to sell. This disclosure is based solely on the seller's observation and knowledge of the property's condition and the improvements thereon. This disclosure form shall not be a warranty by the seller or seller's real estate agent and shall not be used as a substitute for an inspection or warranty that the purchaser may wish to obtain. This form is a statement of the conditions and other information about the property known by the seller. Unless otherwise advised, the seller does not possess any expertise in construction, architectural, engineering, or any other specific areas related to the construction or condition of the improvements on the property. Other than having lived at or owned the property, the seller possesses no greater knowledge than that which could be obtained upon a careful inspection of the property by the potential buyer. Unless otherwise advised, the seller has not conducted any inspection of generally inaccessible areas such as the foundation or roof. It is not a warranty of any kind by the seller or by any real estate agent representing any seller in this transaction. It is not a substitute for any inspections. The purchaser is encouraged to obtain his or her own professional inspections.

INSTRUCTIONS TO THE SELLER: (1) Complete all numbered items. (2) Report all known conditions affecting the property. (3) Attach additional pages, if necessary, with your signature and the date and time of signing. (4) Complete this form yourself or sign the authorization at the end of this form to authorize the real estate agent to complete this form on your behalf in accordance with KRS 324.360(9). (5) If some items do not apply to your property, mark "not applicable." (6) If you do not know the answer to a question, mark "unknown."

SELLER'S DISCLOSURE: As seller, I/we disclose the following information regarding the property. This information is true and accurate to the best of my/our knowledge as of the date signed. Seller authorizes the real estate agent to provide a copy of this statement to any person or entity in connection with actual or anticipated sale of the property or as otherwise provided by law. The following information is not the representation of the real estate agent.

Please answer all questions. If the answer is yes, please explain. If additional space is needed, use the reverse side or make attachments. **I.** HOUSE SYSTEMS

1.		y past or current problems affecting: N/A	YES	NO	UNKNOWN
		Plumbing		v	
	(h)	Electrical system	0.0000000	<u>X</u>	
	(c)	Appliances.		X	
		Floors and walls Soo attachment		<u>_X</u>	
	(u)	Floors and walls. See attachment.		X	
	(9)	Colling and ettic for		_X_	
	(f)	Ceiling and attic fans		<u>_X</u>	
	(g)	Security system		_X_	
	(h)	Sump pumpX			
	(1)	Chimneys, fireplaces, inserts		<u>_X</u>	
	(j)	Pool, hot tub, sauna			
	(k)	Sprinkler systemX HeatingS.e.eAFFachment_age Cooling/air conditioning.Attachment_age			
	(1)	Heating See. AFTachment age			
	(m)	Cooling/air conditioning Attachmentage			
	(n)	Water heaterage 4/27/2015			
		Explain:			
2.	FO	UNDATION/STRUCTURE/BASEMENT N/A	YES	NO	UNKNOWN
Concession of the		Any defects or problems, current or past, to the foundation or slab?	ILS	NU	UNKNOWN
	(h)	Any defects or problems, current or past, to the structure or exterior veneral		<u>_X</u>	2 <u>4</u>
	(0)	Any defects or problems, current or past, to the structure or exterior veneer?			
	(c)	Has the basement leaked at any time since you have owned or lived at the property?		х	
	(d)	When was the last time the basement leaked? <u>Never leaked</u>		<u></u>	
	(e)	Have you ever had any repairs done to the basement?		Х	
	(f)	If you have had basement leaks repaired, when was the repair performed?	· · · · · · · · · · · · · · · · · · ·		
	(1)				
		Explain:			
Initials (Se	ller)	DN/AN Date/Time_01/13/2020 Initials (Buyer) Date/Time Form M	105 revised 3	3/2016	Page 1 of 4

		If the basement presently leaks, how often does it leak? (e.g., every time it rains,				
	(h)	only after an extremely heavy rain, etc.)	-0			
	(11)	regard to the crawl space?	·		<u> </u>	
3.		DOF	N/A	YES	NO	UNKNOWN
	(a)	Age of the roof covering? 09/2003	_			
	(b)	1. Has the roof leaked at any time since you have owned or lived at the property?		<u>_X</u>		
	(-	2. When was the last time the roof leaked? <u>12/2014</u>		v		
	(C	1. Have you ever had any repairs done to the roof?	014	<u>_X</u>		
	(d)	<ol> <li>If you have ever had the roof repaired, when was the repair performed? <u>12/2</u></li> <li>Have you ever had the roof replaced?</li> </ol>	014	х		
	(u)	2. If you have had the roof replaced, when was the replacement performed? $\frac{9}{0}$	2			
	(e)	If the roof presently leaks, how often does it leak? (e.g., every time it rains, only aft				
	. ,	an extremely heavy rain, etc.) The roof presently does not leak.				
	(f)	1. Have you ever had roof repairs that involved placing shingles on the roof instead	-			
		of replacing the entire roof covering?			_X	
		2. If yes, when was the repair performed?				
		Explain:	-			
4.		ND/DRAINAGE	N/A	YES	NO	UNKNOWN
	(a)	Any soil stability problems?			x	
	(b)	Has the property ever had a drainage, flooding, or grading problem?			_X_	
	(c)	Is the residence located within a Special Flood Hazard Area (SFHA) mandating the				
		purchase of flood insurance for federally backed mortgages?	··		<u>    X</u>	
	(4)	If yes, what is the flood zone?	- 8			
	(a)	adjoining this property?			V	
		Explain:			<u>_X</u> _	
		Explain				
5.		UNDARIES	N/A	YES	NO	UNKNOWN
	(a)	1. Have you ever received a staked or pinned survey of the property?		_ <u>X</u>		
		2. Are the boundaries marked in any way?		x		20 <u>00</u>
		3. Do you know the boundaries? If yes, provide description below	·	X		
	<b>(</b> 1)	Explain: We have a land plot map.	_			
	(0)	Are there any encroachments or unrecorded easements relating to the property of which you are aware?			V	
		which you are aware? Explain:	·		<u>_X</u>	
6.	w	ATER	N/A	YES	NO	UNKNOWN
•••••	100000	1. Source of water supply Georgetown Water	INA	ILS	NO	UNKNOWN
	()	2. Are you aware of below normal water supply or water pressure?	-		Х	
	(b)	Is there a water purification system or softener remaining with the house?	• • • • • • •	x	<u>~</u>	
	(c)	Has your water ever been tested? If yes, provide results below			X	
		Explain:	_			
7.	SE	WER SYSTEM	N/A	YES	NO	UNKNOWN
	(a)	Property is serviced by:				onderioni
		1. Category I. Public Municipal Treatment Facility	_X_		-	Paralle Alt
		2. Category II. Private Treatment Facility	. <u>X</u>	1000 C		
		3. Category III. Subdivision Package Plant				
		4. Category IV. Single Home Aerobic Treatment System ("Home Package Plant")	<u>X</u>			
		5. Category V. Septic Tank with drain field, lagoon, wetland, other onsite dispersal 6. Category VI. Septic Tank with dispersal to an offsite, multi-property cluster		<u> </u>		
		treatment system	v			
		7. Category VII. No Treatment/Unknown	·^			
		Name of Servicer (if known):				
	(b)	For properties with Category IV, V, or VI systems:	-3			
		Date of last inspection (sewer):				
		Date of last inspection (sentic): 2016 Date last cleaned (sentic): 2016				
	(c)	Are you aware of any problems with the sewer system?	X			
		Explain:				
1.4.1.4		140 m. 01/12/2020				
Initials (Se	ener)	AN Date/Time_D1 13 2020 Initials (Buyer) Date/Time	Form M10	)5 revised 3	3/2016	Page 2 of 4

<ul> <li>(b) Wer Exp</li> <li>9. HOME <ul> <li>(a) 1. Is</li> <li>2. If</li> <li>3. H</li> <li>H</li> <li>(b) Are</li> <li>asses</li> <li>(c) Are</li> <li>such</li> <li>Expl</li> </ul> </li> <li>10. MIS <ul> <li>(a) Was</li> <li>(b) Are</li> </ul> </li> </ul>	e there been any additions, structural modifications, or other alterations made? e all necessary permits and government approvals obtained?ain:	N/A X	 YES 	× NO 	UNKNOWN
<ul> <li>9. HOME         <ul> <li>(a) 1. Is</li> <li>2. If</li> <li>3. H</li> <li>H</li> <li>(b) Are</li> <li>asses</li> <li>(c) Are</li> <li>such</li> <li>Expl</li> </ul> </li> <li>10. MIS         <ul> <li>(a) Was</li> <li>(b) Are</li> </ul> </li> </ul>	DWNER'S ASSOCIATION         the property subject to rules or regulations of a homeowner's association?         yes, what is the yearly assessment?       \$	<u>_x</u>		NO 	UNKNOWN
(a) 1. Is 2. If 3. H H (b) Are asse: (c) Are such Expl 10. MIS (a) Was (b) Are	the property subject to rules or regulations of a homeowner's association? yes, what is the yearly assessment? \$	<u>_x</u>			
3. H H (b) Are asses (c) Are such Expl 10. MIS (a) Was (b) Are	DA Primary Contact Name:	8 0 5 	_		
3. H H (b) Are asses (c) Are such Expl 10. MIS (a) Was (b) Are	DA Primary Contact Name:	8 0 5 		v	
(b) Are asses (c) Are such Expl 10. MIS (a) Was (b) Are	you aware of any condition that may result in an increase in taxes or sments?				
(c) Are such Expl 10. MIS (a) Was (b) Are	sments?	·		v	
(c) Are such Expl 10. MIS (a) Was (b) Are	sments?	·	_		
(c) Are such Expl 10. MIS (a) Was (b) Are	any features of the property shared in common with adjoining_landowners as: walls, fences, driveways, etc? ain:			х	
Expl 10. MIS (a) Was (b) Are	ain:				
(a) Was (b) Are			<u>_X</u>		
(b) Are	CELLANEOUS	N/A	YES	NO	UNKNOWN
(b) Are	this house built before 1978?			x	
naini	you aware of any use of urea formaldehyde, asbestos materials, or lead based		000000000		
(a) 1 A	in or on this home?	·		<u>_X</u> x	
	e you aware of any testing for radon gas?sults, if tested			<u>_X</u>	
(d) Are	sults, if tested	c			
or at	andoned wells on the property?	3	х		
(e) Are	here any other environmental hazards known to seller? (e.g., carbon monoxide,				
haza	dous waste, water contamination or methamphetamine contamination)			Х	
L	to properly disclose methamphetamine contamination is a Class D Felony under		24.99-01	0.	
	ou aware of any present or past wood infestation (e.g., termites, borers, carpent fungi, etc.)?			<u>_X</u>	
(g) Are	ou aware of any damage due to wood infestation?			x	
(h) 1. Ha	s the house or other improvements ever been treated for wood infestation?			x	
2. If	ves, when, by whom, and any warranties?				
(i) Are	ou aware of any existing or threatened legal action affecting this property?			X	
(j) Are t	here any assessments other than property assessments that apply to this property				
(e.g.,	sewer assessments)?			<u>_X</u>	
(k) Are	ou aware of any violations of local, state, or federal laws, codes, or ordinances			~	
(1) Are v	ng to this property? ou aware of any other conditions that are defective with regard to this			<u>x</u>	
	rty?			Y	
(m)	Are there any environmental hazards known to seller? E.g., methamphetamine			<u>^_</u>	
conta	mination?			X	
00000	mination?		X		
(n) Are t	his house ever been damaged by fire or other disaster (e.g., tornado, hail, etc.)?			<u>X</u>	
(o) Has 1	, please explain:			v	
(o) Has t	VI AWALS OF THE EXISTENCE OF THOM OF OTHER THIND ON THE DRODERTY /			X	
(o) Hast If yes (p) Are y	his house ever had pets living in it?		V		
(o) Hast If yes (p) Are y (q) Hast	his house ever had pets living in it?		x		_

#### SPACE FOR ADDITIONAL INFORMATION

	anna da conto o caco de internet de term			
		Mi - Eleger stat el tractar tractar		
			ne andre de la companya de la compan National de la companya de la company	
			2000, 25 - 19 van se sanda berd kielen er ens	
Seller states that the information contained i his/her/their knowledge and belief. Seller age prior to closing by providing a written adde	ees to immediately	Property Condition notify Buyer of an	Form is complete and accurate y changes that may become kn	to the best of own to Seller
		Л		
Donul hohm	<u>1/13/202</u> 0 Date	Seller	yse Mahum 11	13/2020 Date
			, ,	
**************************************	ERE, ND HAS DONE SO	. SELLER HERE	HAS BEEN REQUEST BY AGREES TO HOLD HAR	ED BY THE MLESS THE
KRS 324.360(9).				
Seller:		Date		
**************************************				
Seller:		Seller:		
Date:		Date:		
**************************************				
Broker/Real estate agent:			Date:	
THE BUYER ACKNOWLEDGES RECEIPT	OF THIS FORM.			
Buyer	Date	Buyer		Date
THIS FORM PROVIDES THE MINIMUM D INFORMATION NOT REQUESTED ON TH	ISCLOSURES REQU IS FORM AND MAY	JIRED BY LAW. SI 7 RESPOND TO AI	ELLER MAY DISCLOSE ADDI DDITIONAL INQUIRIES OF TH	TIONAL IE BUYER.
Initials (Seller) Date/Time	Initials (Buyer)	Date/Time	Form M105 revised 3/2016	Page 4 of 4

January 11, 2020

#### 1. HOUSE SYSTEMS

- (d) Drywall repair in some areas is done, several walls and ceilings were painted. New paint on basement and crawl space walls. All paint jobs were completed in October 2019.
- (e) All French doors, entrance and garage doors were realigned, new seals, new thresholds and water reflector seals were installed in September 2019.
- (I) & (m) We have four heat pumps for heating and air conditioning:
  - 1. Bryant model 336239-701 Installed 10/29/2009
  - 2. Bryant model 335684-701 Installed 10/29/2009
  - 3. Carrier heat pump Installed 11/03/2010
  - 4. Carrier heat pump Installed 04/10/2019

All units installed and serviced by Georgetown Air (George Riebel)

#### 2. FOUNDATION/STRUCTURE/BASEMENT

(b) Dryvit was repaired in a few places.

The exterior of the house was pressure washed, painted with StoColor Lotusan, September 2019.

This paint was developed for Dryvit. It has a high level of water and dirt repellence, resistance to mold, mildew and algae, UV-stable color retention. All exterior doors, windows and trims were painted in September 2019.

#### 3. ROOF.

(c) Roof replaced on September 2003 due to hail damage on shingles. Roof ventilation replacements and flashing repairs on December 2014 New Chimney caps installed on April 2015

#### 6. WATER

(b) Whole house and drinking water purification systems by Rain Soft. Installed 02/05/2005

#### 7. SEWER SYSTEM

(c) New septic drain lines and d-box installed August 2016

#### **10. MISCELLANEOUS**

- (d) One abandoned covered well.
- (n) Heat pump warranty will be transferred.

All board fences were painted in the Summer of 2019 New motor control board installed on entrance gate.